


2


OFFICE OF THE MUNICIPAL CORPORATION, BHILAI

NIT...

कार्य का नाम - 77 MLD एवं 66 MLD जलशोधन संयंत्र के लिए Non Return Valve प्रदाय कार्य।

SR NO.	Item Code	Description of Item	Unit	Qty	Rate	Amount
1	4.44	Providing & fixing following ductile iron double flanged check valve without damper (non-return valve) including jointing & testing with cost of jointing material such as bolts, nuts and rubber insertion all complete as per IS: 5312 (Part II)				
		300 MM Dia	Each	3		
		350 MM Dia	Each	6		


Ass. Engineer
Municipal Corporation
Bhilai


Sub Engineer
Municipal Corporation
Bhilai